TECHNICAL NEWS

Bulletin Nbr: 98-11-248

Date: NOVEMBER 1998

Market: ALL

Test cable assembly

Cars affected

Saab 9-3 Diesel

Background

It has been found that a number of test cable assemblies, part No. (16) 86 12 319, are defective.

Procedure

Check the cable assembly by connecting a multimeter to pin 105 at both ends. If there is continuity between the pins, the cable assembly is OK. If not, put in a claim for the cable assembly in the usual manner.

11/3/01