

SERVICE INFORMATION

Number: 212-1324

Year: 1993

Month: FEBRUARI

Market: ALL

Noise due to pistons fitted the wrong way round

Cars concerned

Saab 900 and Saab 9000 models

Background

A number of cars that have developed a pronounced noise in the engine, which is due to pistons having been fitted the wrong way round.

Procedure

- On cars that have been driven 20.000 km or less, the remedial action is to turn the pistons the right way round.
- On cars that have been driven more than 20.000 km, change the pistons that have been fitted the wrong way round. Check that the cylinder barrels are not scored or damaged.

For a more detailed description of this work, refer to section 212 of the Service Manual.