

SERVICE INFORMATION

Number: 363-1459

Year: 1993

Month: DECEMBER

Market: ALL

Risk of blocked windscreen washer hose

Cars concerned

Saab 900 M94-

Background

If the washer is removed from the plastic grommet in the cover on the top of the false bulkhead space, it is very important that the washer hose be refitted correctly.

If the washer hose is twisted more than 1/4 turn in relation to its previous orientation, there is a great risk that the hose will become kinked, causing a blockage.

Procedure

To eliminate the risk of the washer hose becoming blocked the washer hose and the plastic grommet should be marked prior to removal to indicate their relative position.

