

SERVICE INFORMATION

Bulletin Nbr: 850-2000
Date:.....DECEMBER 1998
Market: US

Affixing airbag label



D850B603

Legislation-related modification campaign 10706

Cars in stock must be rectified before delivery.

Owners of cars already delivered must be informed of the fault by means of a personal communication requesting them to affix the enclosed label on their driver's side sunvisor.

Cars affected

All 3D/5D with VIN from X2000095 to X2007026 inclusive

All CV with VIN from X7000063 to X7002698 inclusive

Background

A label concerning information on the airbag must be affixed to both the driver's and passenger's sun visor in order to comply with requirements in FMVSS 208. (Passenger side label already installed.)

Parts required

50 10 103 Label

Procedure

Fit the label in the position shown in the illustration.

A= 24 5 (3D/5D) or 30 5 (CV)

Warranty/Time Information

See separate information.