

**TECHNICAL NEWS**

Bulletin Nbr: 98-12-365

Date:.....DECEMBER 1998

Market: ALL

**DICE activates the hazard flashers**

**Cars affected**

Saab 9-3 up to VIN X2030478 (3D, 5D), and VIN X7024091 (CV).

**Background**

Due to the manufacturing process used by the supplier, one of the capacitors in the DICE can fail and cause the hazard flashers to light without cause.

**Procedure**

Change the DICE unit as described in WIS.