

TECHNICAL NEWS	
Number:	99-01-371
Year:	1999
Month:	JANUARY
Market:	ALL

Fault diagnosis hints related to grounding points G41S and G41P

Cars affected

Saab 9-5

Background

Grounding point G41 may be making bad contact on certain cars.

This will become apparent through different symptoms, such as the SID message "TRANSMISSION OVERHEATING" and/or problems with the Winter or Sport switches.

Procedure

If an electrical fault is suspected, check that the ground cables connected to grounding points G41S and G41S are making good contact. Both are located behind the radio, G41S on the left-hand side in the centre of the knee member and G41P on the right-hand side in the centre of the knee member.