SERVICE INFORMATION

Number: 234-1876

Year: 1997

Month: DECEMBER

Market: ALL

	Fue	el 1	filler	pipe.	new	screw
--	-----	------	--------	-------	-----	-------

Cars affected

Saab 900 3D/5D M94- up to and including VIN W2010511.

Saab 900 CV M95- up to and including VIN W7004781.

Background

The 13 mm hexagon polymer screw securing the fuel filler pipe to the body has been replaced with a new 6 mm hexagonal socket screw. This is to reduce the risk of the screw inadvertently being over-tightened.

Parts required

49 40 896 Plastic screw

Procedure

Always fit the new screw (1), part no. 49 40 896, when carrying out work where the fuel filler pipe must be removed/refitted or if the screw has been damaged.

Tightening torque: 1.5 Nm (1.1 lbf ft)

Reference: S0234187601 10/28/01 Page 1 of 1