

SERVICE INSTRUCTION
Number: 850-2001
Year: 1998
Month: JULY
Market: US

Affixing airbag label

Legislation-related modification campaign 10706

Cars in stock must be rectified before delivery.

Owners of cars already delivered must be informed of the fault by means of a personal communication requesting them to affix the enclosed label on their driver's side sun visor.

Cars affected

All cars within VIN interval X3000515 to X3003973 inclusive

Background

A label concerning information on the airbag must be affixed to both the the driver's and passenger's sun visor in order to comply with requirements in FMVSS 208. (Passenger side label already installed.)

Parts required

50 10 103 Label

Procedure

Fit the label in the position shown in the illustration.

Warranty/Time Information

See separate information.