SERVICE INSTRUCTION


Number: 113-2084

Year: 1999

Month: FEBRUARY

Market: ALL

Changes to Saab Original Service Programmes



Cars affected

All cars with removable towbar attachment.

Background


When fitting the towbar attachment, there is a danger of it not locking correctly to the coupling pin if the pin is dirty or inadequately greased.

Materials

16-30 20 476 Molycote 33 grease

Measure

Clean the coupling pin as necessary. Grease the coupling pin at every service interval with Molycote 33. Check that the towball unit is easy to fit and remove and that it locks securely.



11/18/01 Page 1 of 2

Put this amendment in Service Manual group 1, Service, under the heading Lubrication.

900 manual: page 73.9-3 manual: page 85.9-5 manual: page 78.

Reference : X9533 11/18/01 Page 2 of 2