**SERVICE INFORMATION** 

Number: 010-1769

Year: 1997

Month: MAY

Market: ALL

## Amendments to contents of service bulletins (SI/MI)

## Disclaimer of incorrect usage

• Certain markets require all service bulletins to include a disclaimer which specifies the purpose and warns against incorrect usage. To satisfy this requirement as efficiently as possible, the first page of all service bulletins (SI/MI) will in future carry the following text:

Saab Automobile AB Bulletins are intended for use by professional Saab technicians only, NOT a "do-it-yourselfer". They are designed to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Saab trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have the condition. See your authorized Saab Dealer for information on whether your vehicle may benefit from the information.

© 1997 Saab Automobile AB. All rights reserved.

ENG

Since a corresponding requirement applies to the WIS (Workshop Information System), which is that part of EPSI which covers service information, the above text will be available in connection with both on-screen presentation and paper printouts of SI/MI service bulletins.

## Warranty/Time Information

Since Saab's forthcoming EPSI information system is specified and developed for application on a global scale to as great an extent as possible, we must therefore adapt and standardize certain terminology to make it as clear and unambiguous as possible.

In most of the different language versions the changes are only minor and affect neither the significance of the codes nor their application. Headings and text in the Standard Time List will be reviewed at the same time in order to bring about the adaptation of current terminology.

The changes that have been introduced, and which from now on will be used in future SI/MI, entail an alteration in the layout of the Standard Time Information/Warranty Information, as shown below.

Failed Object:
Fault/Reason code:
Location code:
Warranty Type (US)

Warranty/Time Information

Repair/Action code:

Labour Operation (US):

Time:

Reference: S234552A 10/27/01 Page 1 of 1