

**SERVICE INFORMATION**


**Number:** 103-1813

**Year:** 1997

**Month:** SEPTEMBER

**Market:** US, CA

**New Special tool: ignition discharge module**



Test module: 83 95 279 (CA: 30567748)

For more detailed instructions, see Service Information No. 340- 1722