

SERVICE INFORMATION

Number: 211-9005
Year: 1994
Month: FEBRUARY
Market: US

Engine Gaskets

Background

The following list of parts are being discontinued and are now replaced by sealant, P/N 02 44 970 (Loctite 518 Anaerobic sealer). Use of this sealant will eliminate any chance of oil leakage. Part numbers listed below **will not automatically supersede** to the newer number-you must order as needed.

Materials

Loctite 518 Anaerobic seal: 02 44 970 (50ml tube: enough to do more than one car)

Replaces:

End plate gaskets	75 63 661
	75 16 586
	75 63 679
	93 54 267
Timing cover gaskets:	91 17 839
	91 17 060
	75 63 653
	75 09 375
	93 56 957
	93 07 836
	83 59 325
	75 88 882
	91 17 847
	75 63 646

75 09 367

93 07 828

75 88 890

Because P/N 02 44 970 comes in a 50ml tube (enough for more than one car), it will not come in the following gasket kits and should be ordered separately.

B201 engine gasket kits:

93 37 213

93 37 221

Loctite 518 is also available locally. Check with your automotive suppliers.