

SERVICE INFORMATION

Bulletin Nbr: 248-2243

Date:.....Maj 2000

Market: all

Not possible to program Trionic T7**Cars affected**

All Saab 9-5

Saab 9-3 with Trionic T7

Background

The control module included in the spare parts kit for electronic unit T7 has been changed and therefore received a new part number. This part number was not included in the register of earlier versions of TIS 2000.

When attempting to update new hardware with an older version of TIS 2000, the error message "No appropriate software available" will be displayed and it will not be possible to carry out any programming.

Parts required

Enclosed CD, Saab TIS 2000, SPS version 7.0 Tech 2 version 36.000.

The information on this disc will also be included in the next ordinary edition of WIS.

Procedure

1. Insert the CD into the drive on your computer.
2. Run the TIS 2000 installation.