	SERVICE INFORMATION	
Number:	631-1721	
Year:	1996	
Month:	DECEMBER	
Market:	ALL	

Amendment to text on wear limits in Service Manual 6 "Front assembly and steering"

Procedure

"Wear limits" in the Technical Data section should be deleted and replaced with:

IMPORTANT

"No free play should be visible when the front assembly is relieved of load."