



SERVICE INFORMATION

Bulletin Nbr: 853-1751

Date:.....MAJ 1997

Market: ALL

Spacer washers as spare part for side consoles, seat-belt member



D853B612

Cars concerned

Saab 900 5d M97- from chassis number V2020500.

Background

The body width varies between the 3- and 5-door cars. In order to avoid that the side console and the seat-belt member make contact during assembly, spacer washers in the materials kit as a spare part must not be used on 5 door cars.

Materials

44 14 033 Side console, left

44 14 041 Side console, right

Procedure

When replacing the side console on 5-door cars, first check if there is a spacer washer behind the side console.

S<H?? ?.. Bulletins - SI/MI - (853-1751) Spacer washers as spare part for side consoles, seat-belt member

- If the car lacks a spacer washer, the spacer washer included in the materials kit must not be fitted.
- If there is a spacer washer, it should be refit.

Warranty/Time information

Failed Object: 85362

Fault/Reason code: -

Location code: 09

Repair/Action code: 01

Time: -

Warranty information

Normal warranty regulations apply.