

**SERVICE INFORMATION****Number:** 937-1673 UTG. 2**Year:** 1996**Month:** APRIL**Market:** ALL**Error in fitting instructions for Wiring harness, trailer, operation****Part No. 400 101 242**

In the Aug 94 edition of fitting instructions 75 04 06 the wrong colour of the 33- pin connector in point 9 is given.

The correct colour is grey . The text should then read as follows:

- 1 Cut off the VIOLET lead on pin 13 in the 33-pin connector (Grey connector).

This correction has been introduced with effect from the fitting instructions dated Oct 95.