

**TECHNICAL NEWS**

Bulletin Nbr: 98-09

Date:.....SEPTEMBER 1998

Market: ALL

**Incorrect indication of tyre size on Tech2****Cars affected**

All Saab 9-3.

**Background**

There have been reports of incorrect MIU programming of tyre size. The tyre size shown on Tech2 is not the same as fitted on the car.

Alternatives are 195/60x15, 205/50x16. These are also the same radius.

**Procedure**

The rolling radius is the same for both alternatives. No reprogramming is required.