

**TECHNICAL NEWS**

Bulletin Nbr: 99-02-852a

Date:.....February 1999

Market: all

**New memory contact for front seats**

**Cars concerned**

All 9-3 with electrically adjustable front seats with memory function.

VIN:

9-3 3D/5D M98-M99 up to and including X2053479

9-3 CV M98-M99 up to and including X7050225

**Background**

It is possible that the driver comes in contact with (or sits on) the memory buttons while entering or exiting the car. Several cases of door mirrors changing position without cause have been reported by customers. On occasions when the "M"-button has been disturbed, the programmed position has also changed.

**Procedure**

To avoid undesired changes in mirror position and reprogramming of previously stored memory settings, a new switch unit with higher rim around the buttons has successively been introduced in production during model year 1999.

The new switch unit has the same part number as the old one and can be ordered from the order department in Nyköping.