

TECHNICAL NEWS

Bulletin Nbr: 99-02-855c

Date:.....February 1999

Market: all

Fitting bottom steering column cover

Car affected

Saab 900 M94- and Saab 9-3

Background

A few cases have been detected in production where the bottom steering column cover has been fitted in such a way that the cables to the dashboard can have been damaged.

Procedure

Pay special attention so that the cables are not pinched when fitting the steering column cover.