

SERVICE INFORMATION

Number: 987-1585 UTG. 2

Year: 1995

Month: NOVEMBER

Market: ALL

Error in fitting instructions 75 02 24 for the Saab compact heater

Cars concerned

Saab 900 M94-.


Background

In point 39 of the fitting instructions, the colours of the leads in the diagram are labelled incorrectly. The text is correct.

Action

Cars on which installation has been carried out as described in edition 1 must be rectified in accordance with this edition.

The orange lead mentioned in point 39 of the fitting instructions is connected between the motor and the plate with the 5- pin connector.



D987B603

Wiring diagram

