


TECHNICAL NEWS

Bulletin Nbr: 98-12-103

Date:.....DECEMBER 1998

Market: ALL

New special tool for removing 5th gear synchromesh hub, manual gearbox



8792640

Cars affected

Saab 9000 M94-, 900, 9-5 and 9-3.

Background

In order to prevent damage to the 5th gear synchromesh hub while removing it, a new special tool has been introduced. The method is described in WIS edition Jan. 99.

The tool is supplied with laminate and holder for special toolboard T-4, manual gearbox (half board) and is to hang between coordinates C / D and 6 / 7. The tool is an A2 subscription tool and will be delivered automatically to subscribers, while others must order according to applicable procedures.

Tools

(16) 87 92 640 Fitting tool