

SERVICE INFORMATION

Number: 860-1455

Year: 1993

Month: NOVEMBER

Market: ALL

Scratches on bumper cover

Cars concerned

Saab 900 M1994-

Background

In the event of minor scratches on the unpainted bumper cover it is unnecessary to change it. The scratches can be removed by polishing. Minor scratches are all marks on the bumper cover where the material itself has not been damaged.

Materials

Cellulose thinner Cloth

Action

Polish the bumper casing with the cloth and thinner.

Standard time information

Object code: 86140/86150

Fault code: 83

Localization code: 09

Action code: 07

Time: 0.1

Warranty information

Standard warranty rules apply.