

TECHNICAL NEWS

Bulletin Nbr: 99-09-101

Date:.....September 1999

Market: all

WIS-installation

Cars affected

All Saab 900, 9-3 and 9-5

Background

It has become evident that workshop information must be installed in a special order to avoid newer versions of certain files being written over and replaced by older versions.

Procedure

It is important that the WIS-installation is carried out in the following order: 900, 9-5, 9-3.

The latest edition of the WIS CD should always be installed last.